

DATASHEET



ESD Wristband Tester With Wall Mount And Footplate

SKU: G093-0019C



Description

This wristband tester has been designed to measure both high and low fail and pass functions. It also has a low battery indicator to indicate battery replacement. Testing of your wristband is achieved by placing the jackplug into the socket and wearing the wristband - touch the touchplate and the status of the wristband will be shown. Can be powered by a 9 volt PP3 alkaline battery. The product is CE approved.

Features: • Lower Limit 750k +/-10%

- Upper Limit 35Meg +/-10%
- Power 9V alkaline battery

Specifications:

	[
Power Supply	9-volt PP3 alkaline battery. (PSU-02 9 volt 100mA UN-regulated)
Test Voltage	Nominal 9 volts-stepped to 100 volts
Temperature Range (40°F to 120°F)	Operating 5°C to 49°C Storage -15°C to +60°C
Relative Humidity	0% to 90% (non-condensing)
Accuracy	+/- 10%
Repeatability	+/- 10%
Weight	150g
Dimensions of Tester	130mm x 70mm x 25mm